



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah


## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program July 20, 2011

Reviewed: 

<b>Mine Name:</b> Leamington Cement Plant	<b>Permit Number:</b> M/023/0004
<b>Operator Name:</b> Ash Grove Cement Company	<b>Inspection Date:</b> July 14, 2011
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 9:00 -11:00 AM
<b>Other Participants:</b> Josh Nelson	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection.

#### Inspection Summary:

The Permittee is current on permit fees. The bond amount is for \$4,526,300 and the renewal date is July 22, 2012.

The mine site bisects a State highway. The Permittee placed warning signs to alert the public to the hazards associated with the mine.

The highwalls appear stable and there are no signs of failure.

The site is a total containment site. There is no sign that water left the site.

The Permittee is in the process of expanding the pit to the south.




**Conclusions and Recommendations:**

**Inspector's Signature**


WHW

cc: (OPERATOR)


A handwritten signature in blue ink, appearing to read "Wayne White", is written over a horizontal line.

O:\M023-Juab\M0230004-Leamington\Inspections\Insp-07142011.doc






Working pit with expansion to the south




Highwalls and terraces





Pit looking north



Cement Plant